


FIG. 1



Modularized  
Architecture

FIG. 2




FIG. 3





FIG. 4



EDA System 511

15

231

四





FIG. 6






FIG. 7




سیپ سیزدهم


FIG. 8




## Setup Phase



## Execution Phase



**FIG. 9**



**FIG. 10**




FIG.11




FIG. 12

1360



1310





FIG 13

AN



**FIG. 14**

De-norm fix w/ us




FIG. 15




FIG. 16




FIG. 17

1810 **GraphPoint Detail Window**General Information 

## General

Value: 0.524400  
 UCL: 0.5  
 Target: 0.48  
 LCL: 0.46  
 PCS Recipe: Metal 5  
 RunId: 106537  
 OOC Violation: One Out Above(WE Control Rules)

Attribute	Value
Lot	J105M20
Operation	9110
Product	6308AC
Measurement Time	2001-04-25 13:32:04
Opal	CD12
Batch	

## Out-Of-Control Actions

Action	Correct	Message
SHUTDOWN TOOL	BRING BACK TOOL	
HOLD LOT	RELEASE LOT	
EMAIL		

## Annotation History

Time	Creator	Annotation

1820 Add 1821

Done

**FIG. 18**

1800 ↗





FIG. 19



**FIG. 20**